


Dalgety Bay

Appropriate Person Report


Appendix 16

Author	Miss Nina Patton		26 June 2013
Reviewed	Dr James Gemmill		27 June 2013
Approved for Release	Ms Janice Milne		27 June 2013



Cross section lines and trial pit/borehole locations after AMEC Factual Investigation Report 2013.
Coastlines after Sneddon et al, 2013.

Figure B0



Cross section line and trial pit/borehole logs after AMEC Factual Investigation Report 2013.

Coastline locations after Sneddon et al, 2013.

Figure B1

Cross section line and trial pit/borehole logs after AMEC Factual Investigation Report 2013.

Coastline locations after Sneddon et al, 2013.






Figure B3



Cross section line and trial pit/borehole logs after AMEC Factual Investigation Report 2013.

Coastline locations after Sneddon et al, 2013.


Figure B2



Cross section line and trial pit/borehole logs after AMEC Factual Investigation Report 2013.

Coastline locations after Sneddon et al, 2013.


Figure B4



Cross section line and trial pit/borehole logs after AMEC Factual Investigation Report 2013.

Coastline locations after Sneddon et al, 2013.

Figure B5



Cross section line and trial pit/borehole logs after AMEC Factual Investigation Report 2013.

Coastline locations after Sneddon et al, 2013.

Figure B6